



PROTO INDUSTRIAL TOOLS 2195 E. View Parkway, Suite 103 Conyers, Ga. 30013 Phone (770) 787-3800 FAX (770) 385-3708 www.stanleyworks.com

Operation continued

Memory needle clockwise operation

1. Rotate the bezel (1) in the counter clockwise direction until the memory needle (2) hits the pointer needle (3). Continue to rotate the bezel until the memory needle points to zero on the scale to be used.

2. Apply torque in the clockwise direction. The pointer needle will push the memory needle as torque is applied.

3. When the memory needle reaches the desired value, stop applying torque. The pointer needle will return to zero and the memory needle will stay at the maximum torque applied.

4. After reading the torque value, reset the memory needle by rotating the reset knob (4), in the counterclockwise direction, until the memory needle touches the pointer needle.

5. Make sure the memory needle is pointing to zero, by rotating the bezel in the counterclockwise direction, before starting another torque cycle.

Memory needle counter-clockwise operation 1. Rotate the bezel (1) in the clockwise direction until

the memory needle (2) hits the pointer needle (3). Continue to rotate the bezel until the memory needle points to zero on the scale to be used.

2. Apply torque in the counter-clockwise direction. The pointer needle will push the memory needle as torque is applied.

3. When the memory needle reached the desired value, stop applying torque. The pointer needle will return to zero and the memory needle will stay at the maximum torque applied.

4. After reading the torque value, reset the memory needle by rotating the reset knob (4), in the clockwise direction, until the memory needle touches the pointer

5. Make sure the memory needle is pointing to zero, by rotating the bezel in the clockwise direction, before starting another torque cycle.

Safety Warnings Read Prior To Use!

wear safety glasses when using this torque

Out of calibration torque wrenches may cause damage to the part or the torque

Do not use cheater bars to apply force to the

Do not exceed the maximum range of the torque wrench

Apply torque in a safe manner that will not result in injury or fall if the fastener or wrench should slip or break. Pulling on the wrench, as opposed to pushing, may help avoid injury if breakage should occur.

while applying torque. Your feet should be firmly placed on the ground so if the wrench should slip or break you will not fall.

to the handle

Caution-Ratchet

parts are worn, dirty, mismatched, or if the direction lever is not fully engaged.

The operator and bystanders should always


Periodic recalibration of this torque wrench is required to ensure accuracy

Never use the wrench to balance your weight

Never "bounce" on the wrench to apply force

Ratchets may slip or break, causing injury, if

Use of Adapters



When using an extension adapter, like what is shown, the actual torque applied (AT) will be greater than the reading shown on the dial (DR). Use this formula to determine the actual torque applied:

AT=DR(L+A)/L

AT=Actual Torque DR=Dial Reading A=Length of Extension L=Length from hand position to center of square drive

The extension should only be used in-line with the wrench (as opposed to being at an angle), or the above equation does not apply.

Operation



1. Bezel 2. Memory needle 3. Pointer needle 4. Reset knob 5. Outer scale 6. Inner scale

Prior to Use

It is recommended to cycle the wrench to full scale, three times, in the direction to be used, and then set the zero. Dial toque wrenches should be zeroed prior to use. Set zero to proper needle used.

To Set Zero

If you are not using the memory needle feature, rotate the bezel (1) until the pointer needle (3) points to the zero on the scale to be used. If you are using the memory needle feature set the zero as described under memory needle clockwise or counterclockwise operation.

Pointer needle Operation

Apply torque until the pointer needle (3) reaches the desired torque value. When the torque is removed the pointer needle will return to zero (always reset the zero between torque cycles).

Torque Conversion Table

FROM	TO	MULTIPLY BY
lb.in.	oz.in.	16
lb.in.	lb.ft.	0.08333
lb.ln	kg.cm	1.1519
lb.in.	Kg.m	0.01159
lb.in.	N.m	0.113
lb.in.	dN.m	1.13
lb.ft.	kg.m	0.1382
lb.ft.	N.m	1.356
N.M	dN.m	10
N.m	kg.cm	10.2
N.m	kg.m	0.102
oz.in.	lb.in.	0.0625
lb.ft.	lb.in.	12
kg.cm.	lb.in.	0.8681
kg.m	lb.in.	86.81
N.m	lb.in.	8.85
dN.m	lb.in.	0.885
kg.m	lb.ft.	7.236
N.m	lb.ft.	0.7376
dN.m	N.m	0.10
kg.cm	N.m	0.09807
kg.m	N.m	9.807

Certification:

This product, when shipped from the factory, met the accuracy specifications as prescribed in ANSI B107.14M-1994, and was calibrated with equipment that was calibrated with standards traceable to NIST (National Institute of Standards and Technology).